

# Enviromose Pro

## OVERVIEW

Removes sealers and coatings safely and effectively without damaging the surface. Strips a wide variety of surfaces and coatings including:

- Paint & Varnish
- Artex
- Stains & Lacquer
- Graffiti
- Carpet adhesive residues from floors

## BENEFITS

- For internal & external use
- Safer and easy to use
- Water based and non-flammable
- Non-corrosive, non-ozone depleting
- Extra strong for tougher finishes
- Fast acting
- Eco-friendly
- Low VOC

## PRECAUTIONS FOR USE

For Health & Safety instructions, first aid measures, spillages and disposal instructions, see separate Health & Safety Data Sheet (MSDS)

## SURFACE PREPERATION

Always test an inconspicuous area before use to ensure the compatibility and finished result is acceptable. Ensure the surface(s) to be stripped are dry before applying the Enviromose Paintstripper. Protection should be provided for floor coatings that you do not wish to remover or any surface that may be damaged by the remover i.e. perspex, plastics, rubber etc.

## STORAGE

### Keep out of reach of children

Keep in a dry place between 5°C and 30°C in the original container.

## GUIDE OF STRIPPING TIMES

- Varnish:** up to 60 minutes  
**Two pack varnish:** up to 3 Hours  
**Heavy multi-layered paint:** 120 minutes - Overnight  
**Two pack lacquer:** up to 24 Hours  
**Artex:** 1 - 4 Hours

## CLEANING OF EQUIPMENT

Remove as much excess product as possible and clean tools and equipment immediately after use with soapy water.

## PRODUCT CHARACTERISTICS

Colour	White
Odour	Barely Perceptible
Form	Liquid
Specific Gravity @ 25°C	1.01
PH	4/4.5
Shelf Life	24 months from the date of manufacture in the original unopened container
Application Temperatures	Min 5°C, max 30°C
Coverage	1 litre will strip 1-3 m <sup>2</sup> dependant on thickness and amount of layers / coatings to be stripped

## APPLICATION

Cover the top with a cloth during opening to avoid splashes.

Layer a generous, even coat onto the surface to be stripped.

Apply with a suitable clean brush or airless spray. **Do not brush out**

Leave for approximately 2 hours and apply a second generous coat. (On less than five layers of Paint or Varnish, a second coat may not be necessary).

After the product has penetrated the substrate (up to 24 hours) scrape off with a suitable scraper, leaving surface as clean as possible.

Rinse clean with cold water containing detergent and a stainless steel scourer, leave to dry. Never use steel wool - stainless steel only.

**For heavily contaminated surfaces** such as lintels, ledges, old masonry and other substates that are often heavily coated, it is necessary to apply up to 1m<sup>2</sup> per litre of paint remover.

Cover with thin plastic such as cling film or bin liners, proceed to tape the edges.

Leave for a minimum of 24 hours, scrape off excess and rinse clean with cold water containing detergent and a stainless steel scourer.